




FLASH INFORMATION



SALES DIVISION
NETWORK TECHNICAL INFORMATION


ELYSTAR 50cc, 125cc, 150cc

Subject: SPEED READING ERROR FOLLOWING LIGHTING OF THE « CHANGE OIL » MAINTENANCE MESSAGE

Service solution:

The temporary solution for the vehicle speed to read correctly consists in:

1. Clear the maintenance message, to do so, cut off the ignition, press the control button, hold down the control button and turn on the ignition.
2. cut off the ignition.
3. disconnect the battery for at least 30 seconds, the instrument cluster will be reset when the ignition is turned on and the fault will disappear until the next maintenance message appears.



Identification of the new instrument clusters:

On the back of the cluster on the label,

For the Elystar 50cc

- if the date of manufacture (A) is before 17-04-03 and there is a spot of green paint at (B) the instrument cluster is serviceable.
- if the date of manufacture (A) is after 17-04-03 the instrument cluster is serviceable.

For the Elystar 125cc and 150cc

- if the date of manufacture (A) is after xx-xx-xx the instrument cluster is serviceable.

	Dealership	Spare parts	Mechanic 1	Mechanic 2	Mechanic 3
Signature					